

By Ted Blackmore - Squires

Street Audit Survey Record – Location.....Church Street...Basingstoke

Adequacy of access for:

Disability vehicles, prams and pushchairs. At bridge over Churchill Way north entrance gap in rail too tight for disabled vehicles. Wheeled access generally good.

Access for cyclists. good

	Location	Quantity	Quality
Signage and safety			
Signage	good	Are so many street restriction signs necessary?	Remove superfluous post, place parking warning sign on lamp post.
Benches.		One needed at dial a ride	
Waste bins.			Could be better positioned off path line
Other street furniture.			
Planting.			good
Warning surfaces.		ok	good
Non-slip surfaces.		ok	good
Drop kerbs.		ok	good
Mirrors.			
Quality of paths:			
Widths.			good
Slopes.			ok
Repairs			good
Lighting.			good
Surveillance.			

Other remarks:

Rainwater down pipe on town centre wall opposite Office Angles needs repair.