

By Ted Blackmore - Squires

Street Audit Survey Record – Location.....Flaxfield Road...Basingstoke .....

**Adequacy of access for:**

Disability vehicles, prams and pushchairs. Very poor

Access for cyclists. poor

|                           | Location            | Quantity    | Quality   |
|---------------------------|---------------------|-------------|---|
| <b>Signage and safety</b> |                     |             |   |
| Signage                   |                     |             | poor  |
| Benches.                  |                     |             |   |
| Waste bins.               | See underpass audit |             |   |
| Other street furniture.   |                     |             |   |
| Planting.                 |                     |             |   |
| Warning surfaces.         | At new drop kerbs   | 4+          | Pipped tiles  |
| Non-slip surfaces.        | See underpass audit |             |   |
| Drop kerbs.               | Not good            | 8+          | Widen and re-level  |
| Mirrors.                  |                     |             |   |
|                           |                     |             |   |
| <b>Quality of paths:</b>  |                     |             |   |
| Widths.                   | all                 |             | Too narrow, consider pedestrianising whole street east of pinch point |
| Slopes.                   |                     | <b>none</b> |   |
| Repairs                   |                     |             | <b>poor</b>   |
| Lighting.                 |                     | <b>poor</b> |   |
| Surveillance.             | See underpass audit | <b>none</b> |   |

**Other remarks:**

Suggest removing vehicle roadway, install pedestrian paving with coloured paving demarking parking / no-parking areas. Priority to pedestrians and disabled / pushchair / trolley users. Better lighting.